

TVM

| | A | B | C |
|------|------|------|------|
| 1500 | 390* | 395* | 415* |
| 2000 | 390 | 395 | 415 |
| 2500 | 460 | 445 | 485 |
| 3000 | 460 | 445 | 485 |
| 4000 | 485 | 470 | 510 |

Dimensions of the beams are in mm

TVM SH


| | J | K | L |
|------|------|------|------|
| 1500 | 500* | 395* | 415* |
| 2000 | 500 | 395 | 415 |
| 2500 | 570 | 445 | 485 |
| 3000 | 570 | 445 | 485 |
| 4000 | 595 | 470 | 510 |

Dimensions of the beams are in mm

TVM S

| | D | E |
|------|------|------|
| 1500 | 440* | 375* |
| 2000 | 440 | 375 |
| 2500 | 510 | 445 |
| 3000 | 510 | 445 |
| 4000 | 535 | 470 |

Dimensions of the beams are in mm



TVM 3SH

| | M | N | O |
|------|------|------|------|
| 1500 | 500* | 395* | 415* |
| 2000 | 500 | 395 | 415 |
| 2500 | 570 | 445 | 485 |
| 3000 | 570 | 445 | 485 |
| 4000 | 595 | 470 | 510 |

Dimensions of the beams are in mm



*Dimensions are informative.

Other shapes and dimensions of tools consult the manufacturer